

Affected Catalog Part Numbers (CPN)

MCP79410-I/MNY
MCP79410-I/MNYVAO
MCP79410-I/MS
MCP79410-I/S0816K
MCP79410-I/S16K
MCP79410-I/SN
MCP79410-I/SNVAO
MCP79410-I/ST
MCP79410-I/W0816K
MCP79410-I/W16K
MCP79410-I/WF0616K
MCP79410-I/WF0816K
MCP79410-I/WF16K
MCP79410-I/WN BG16K
MCP79410T-I/MNY
MCP79410T-I/MNYVAO
MCP79410T-I/MS
MCP79410T-I/SN
MCP79410T-I/SNV01
MCP79410T-I/SNVAO
MCP79410T-I/ST
MCP79411-I/MS
MCP79411-I/S16K
MCP79411-I/SN
MCP79411-I/ST
MCP79411-I/W16K
MCP79411-I/WF16K
MCP79411T-I/MNY
MCP79411T-I/MS
MCP79411T-I/SN
MCP79411T-I/SNVAO
MCP79411T-I/ST
MCP79412-I/MS
MCP79412-I/S16K
MCP79412-I/SN
MCP79412-I/ST
MCP79412-I/W16K
MCP79412-I/WF16K
MCP79412T-I/MNY
MCP79412T-I/MS
MCP79412T-I/SN
MCP79412T-I/ST