

Eaton

Electronics Division 5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN23006 2/28/2023

CLASSIFICATION OF CHANGE:

FIT

DESCRIPTION OF CHANGE:

Change product label marking. The change eliminates spaces between the markings which point to the negative lead.

V-type
Top View

New Marking

New Marking

FION XXXY

FION XXXY

FION XXXY

FION XXXY

FATO

EATO

Side View

New Marking

FION XXXY

FION XXXY

FATO

EATO

EATO

Side View

REASON FOR CHANGE:

Improve optical machine readability.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. Higher machine read rates in automated systems

PARTS AFFECTED:

KR-5R5H104-R	KR-5R5H474-R	KR-5R5V334P-R
KR-5R5H105-R	KR-5R5V104-R	KR-5R5V334-R
KR-5R5H155-R	KR-5R5V105-R	KR-5R5V474-R
KR-5R5H224-R	KR-5R5V155-R	
KR-5R5H334-R	KR-5R5V224-R	

TIME SCHEDULE:

Start Shipment Date: 5/28/2023 Last Time Buy Date: N/A Last Time Shipment Date: N/A

SAMPLE AVAILABILITY: UPON REQUEST

QUALIFICATION DATA: N/A

ISSUED BY:

Global Product Manager – Jason Lee

CONTACT INFORMATION:

For questions or comments, please Contact us

F202D-02 PCN Rev 02/28/2017